## CHANGE ORDER NO. 1

Owner: Lake County Department of Public Works			Date February 6,2012	
Project FY 2011 Facilities P	ainting Project	· · · · · · · · · · · · · · · · · · ·		
Owner's Contract No. PW 20	)11.040	Contractor: TECORP	INC	
Date of Contract Start 10-5-1	\$ 142,333.00	\$ 142,333.00		
You are directed to make the	following change	s in the Contract Documents. Descr	ription:	
Repair existing cracks at Broo	okside and Route	120 Reservoirs.		
Reason for Change Order: Install Polyurethane grout inj protective coating application		te floor and wall cracks discovered	during prepa	aration in advance of
CONTRACT PR	RICE	C	ONTRACT	TIMES (Calendar
Days)			To substan	
Original:	\$142,333.0	Original:	3/7/2011	3/22/2012
Previous COs (ADD/DEDUCT	Γ):\$ 0	Previous COs (ADD/DEDUCT):		
This C.O. (ADD):	\$14,040.00	This CO (ADD/DEDUCT):		
Contract Price with all approved Change Orders:	\$156,373.00	REVISED:	-	
		Original Completion Date:	3/7/2011	3/22/2012
•		Revised Completion Date:		
The Contractor agrees that this of herein, including all impact, delshall be no further time or dollar of	ays, and acceleration	des any and all costs associated with on costs. Other than the dollar amount esult of this Change Order.	or resulting fron and time allow	n the change(s) ordered rance listed above, there
		COME AN AMENDMENT TO THE CON NANTS OF THE CONTRACT SHALL AF		
RECOMMENOED:  By:	of the		ly from	2
APPROVED: Juliu E.  By: Owner (Authorized Signature)	full	Date	2/19/20	12
ACCEPTED:	$\mathcal{L}$			
By: A House Signal	ture)		-/2	
/ / 3.31.61.	***			



2221 Muriel Court Joliet, Illinois 60433

Phone: 815-726-9192
Fax: 815-726-9245

Email: nvisvardis@tecorp.us

January 12, 2012

Philip Speck Lake County Public Works 650 W. Winchester Road Libertyville, Illinois 60048

Dear Phil,

We propose the following method of repairing the existing cracks at the Brookside Reservoir and Route 120 Reservoir.

**Brookside Reservoir:** Install Polyurethane grout injection to eliminate leaks from (3) each 13.5 tank wall cracks on the east wall per manufacturer's recommendations. At total of 40 LF is figured in the lump sum price.

Lump Sum:

\$6,800.00

Route 120 Reservoir: Install polyurethane grout injection to eliminate leaks 20' of floor to wall joint and 30' of cold joint seam in the floor per manufacturer's recommendations.

Lump Sum:

\$7,240.00

Upon completion of injection process all injection fittings will be revoved and holes patched.

If I could be of further assistance I can be reached on my cell 709-717-9192

Respectfully Submitted

Nick Visvardis

A Complete Professional Coating and Lining Service