## Inspection Status as of July 31, 2020

Inspection Status	# of Projects	
Non-Certified (SMC issued, Forest Preserve, Public Roads )		
Compliant	68	
Non-compliant	17	
Total Inspections	85	
Percent of sites in compliance with the WDO	80 %	
<b>Certified</b> (Public Development in Regulatory Floodplain, Soil Erosion/Sediment Contro Intergovernmental Inspection Assistance)	ol Army Corps Projects,	
Compliant	57	
Non-compliant	6	
Total Inspections	63	
Percent of sites in compliance with the WDO	90 %	



Wetlands Performance Report							
Response Time	Submittals Processed in May 2020Submittals Processed in June 2020			Submittals Processed in July 2020			
Work Days	# Submittals	% Total	# Submittals	% Total	# Submittals	% Total	
> 30 days	0	0%	0	0%	0	0%	
21 - 30 days	0	0%	1	1%	0	0%	
11 - 20 days	4	5%	10	14%	8	9%	
0 - 10 days	82	95%	61	85%	86	91%	
Total Submittals	86	100%	72	100%	94	100%	
Average days	1.60		3.19		2.21		

Stormwater Performance Report								
Response Time	Submittals Processed in May 2020		Submittals Processed in June 2020		Submittals Processed in July 2020			
Work Days	# Submittals	% Total	# Submittals	% Total	# Submittals	% Total		
> 30 days 21 - 30 days	0	0%	2	<u>3%</u>	3	5% 13%		
11 - 20 days	8	9%	6	8%	4	7%		
0 - 10 days	80	91%	69	86%	46	75%		
Total Submittals	88	100%	80	100%	61	100%		
Average days	2.26		3.18		6.03			